Ohio EPA - Daily Discharge Monitoring Report - Form 4500

SUBMISSION ID:

FACILITY:

COUNTY:

DISTRICT:

LOCATION:

27109

SEDO

American Energy Corp Century Mine

43521 Mayhugh Hill Rd Twp Hwy 88

Beallsville, OH 43716

Belmont

STATUS:

Revision

0IL00091*GD PERMIT NUMBER:

STATION CODE: MONITORING PERIOD:

REPORTING LAB:

2008-09-01 To: 2008-09-30 Tra-Det Inc.

ANALYST: Laura K. Wright NO DISCHARGE INDICATOR: AL

Residue, Total **PARAMETER** Dissolved PARAMETER CODE 00515 UNITS 4106 FREQUENCY 1 / 2 Weeks SAMPLING TYPE Grab 2008-09-01 2008-09-02 2008-09-03 2008-09-04 2008-09-05 2008-09-06 2008-09-07 2008-09-08 2008-09-09 2008-09-10 2008-09-11 2008-09-12 2008-09-13 2008-09-14 2008-09-15 2008-09-16 2008-09-17 2008-09-18 2008-09-19 2008-09-20 2008-09-21 2008-09-22 2008-09-23 2008-09-24 2008-09-25 2008-09-26 2008-09-27 2008-09-28 2008-09-29 2008-09-30 Minimum Maximum Average Count Signature of Responsible Official or Authorized Representative Name of Responsible Official I certify under the penalty of law that I have personally examined and am familiar with the information submitted herein and based on my inquiry of those individuals immediately responsible for obtaining the information. I believe the submitted information is true, accurate and complete. I am aware that there are Submission Date/Time or Authorized Representative 2008-10-28 Adam Hartley significant penalties for submitting false information, including the possibility of fine and imprisonment. Page 10